Date: User: Customer First Issue **Previous Run** Written By Seq. #:

Thursday, 27/03/2008 7:35:52 AM Linda Lacelle

Process Sheet

: CC-DAR01 Dart Aerospace Ltd.

Type

Job Number : 38230 **Estimate Number** : 10804

P.O. Number

This Issue : 27/03/2008 S.O. No. :

: NC Prsht Rev.

: // : 00015

Checked & Approved By

Comment

Drawing Name

Part Number Drawing Number : D3562041 · NCR08-027

: D3562-041/-042

Project Number Drawing Revision

Material **Due Date**

: 02/04/2008

Qty:

1 Um: Each

Additional Product

Job Number:



2.0

Machine Or Operation:

Description:

1.0 QC QUALITY CONTROL



Comment: QUALITY CONTROL pull from stock:

D3562-041

: LARGE FAB ASSY

D3562-042 **PACKAGING 1**

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Re-identify the D3562's correctly, using the original batch numbers.

3.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

*** ENSURE BOTH PART AND BATCH #'S ARE CORRECT ***



4.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Re-package as D3562

-041 Qty:

-042 Qty:

FINAL INSPECTION/W/O RELEASE

5.0

QC21

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



08-04-01